

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

M1	Fabric or Cloth
G	Gel
GM	Gel-Sponge or Gel-Foam
M2	Foam or Sponge
M3	Synthetic Resin or Plastic
M4	Fibre
M5	Concrete
M6	Metal or Metal Sponge
M7	Wood
M8	Wire or Screening
M9	Refractory Material
M10	Other Material

Figure 1

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 2a




Figure 2b




Figure 2c




Figure 2d

CONFIDENTIAL




Figure 3a




Figure 3b




Figure 3c




Figure 3d




Figure 3e




Figure 3f




Figure 3g




Figure 3h




Figure 3i




Figure 3j




Figure 3k




Figure 3l




Figure 3m




Figure 3n

100-616260


APPROVED	O.G. FIG.
BY	CLASS SUBCLASS
DRAFTSMAN	

S =

EP =

E =



E =
crystalline



S - E - EP - S

Figure 5

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		



S - EB₄₅ - EP - S

Figure 6


00141-614269

S =

EB₂₅ =

E =


E =
crystalline



S - E - EB₂₅ - S

Figure 7


APPROVED	O.G. FIG.
BY	CLASS SUBCLASS
DRAFTSMAN	

S = 

EP = 

E = 


E = 
crystalline




S - E - EP - E - S

Figure 8


001-61260

S = 

E = 
(non crystalline)

EP = 

E = 
(crystalline)



S - EP - E - EP - S

Figure 9

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Figure 10